



Rusting gusset




Rusting steel angle



Cracking post pockets typical



Cracks extend through wall





Cracked concrete at stair landing




Rusting gusset



Wall cracks need repair and sealing



Failing membrane at previous repair



Tread repair with cracking extending beyond plate



Failed membrane with concrete damage below at aisle stair nosing



Spalled concrete at nosing exposing reinforcing additional concrete ready to break away



Peeling membrane



Spalled nosing



Failed grout pocket typical of numerous locations



Membrane and grout cracked around rim of drain flange



Spalled concrete at tread

Section 9 Membrane deterioration at stairs



Section 8 Row J Temporary Nosing Patch



Temporary nosing cover plate and hole in expansion joint



